

TECHNICAL DATA SHEET

Arco 18 Gauge Cut D Glove

Product Code: 1230000

The 18 Gauge Cut D gloves represents the pinnacle of dexterity whilst continuing to provide a high level of cut protection.

- Pu Coating for robust wear
- 18 Gauge Liner for ultimate dexterity
- Cut level D on ISO13997, perfect for assembly tasks

Sizes 7. 8. 9. 10. 11

Approved to:

BS EN 388:2016 3.X.4.1.D

Suitable For:

- Construction
- Assembly
- General Maintenance
- Packaging
- Engineering

Technical Data:

- 18 gauge Stainless Steel/Hppe liner
- PU coating
- 240mm long

Cuff Colour Sizing:

- 7 – Green
- 8 – White
- 9 – Red
- 10 – Dark Grey
- 11 – Yellow



User

INFORMATION SHEET

Glove description

1230000 18 gauge Cut Level D PU Glove

Approved to:

BS EN 388:2016
BS EN 420:2003+A1:2009
Cat II Intermediate Risk

Product Markings / Performance




Table 1 — Levels of performance

Test	Level 1	Level 2	Level 3	Level 4	Level 5
6.1 Abrasion resistance (number of cycles)	100	500	2000	8000	-
6.2 Blade cut resistance (index)	1.2	2.5	5.0	10.0	20.0
6.3 Tear resistance (N)	10	25	50	75	-
6.4 Puncture resistance (N)	20	60	100	150	-

Obsolescence

When stored properly the product will not suffer changes in the mechanical properties from the date of manufacture. Service life cannot be specified as it depends on the application and its the responsibility of user to ascertain the suitability of the glove for its intended use.

Maintenance

Both new and old gloves should be inspected before wearing to ensure that no damage is present before use. Laundering these gloves is not recommended. If wet allow to dry naturally

Warning

Performance levels relate to the palm area of the glove only. While wearing these gloves please ensure you keep a safe distance away from moving parts of machinery to minimize the risk of entanglement

Innocuousness

Whilst every effort is made to ensure the innocuousness of these products, there are certain chemicals used in the manufacturing process which may cause skin irritation to a small percentage of users. In the unlikely event of this happening, the product should not be used and Arco contacted for alternative products.

Storage and transport

When not in use, store in a well ventilated area away from extremes of temperature Never place heavy items on top of it. If possible, avoid excessive folding and preferably store it hanging vertically

Declaration of Conformity

Declaration of Conformity can be viewed and downloaded from <http://conformity.arco.co.uk>