

TECHNICAL DATA SHEET

Arco Red Cut Control System 1A Foam Nitrile-Coated Gloves

Product Code: 14T3500

Sizes 7.8.9.10

Approved to:

BS EN388:2016 Mechanical Risk 4.X.2.1.A

ISO 13997

BS EN420:2003 Size: 7-10

Suitable For:

- Aerospace
- Automotive
- Manufacturing
- Railways
- General Handling

Technical Data:

- Comfortable 13gg nylon liner offers great dexterity
- Sandy foam nitrile-coated palm enhances grip
- Elasticated knit wrist for secure fit
- Red colour makes it easy to identify the cut protection level at a glance

Cuff Colour Sizing:

- 7 - Green
- 8 - White
- 9 - Red
- 10 - Dark Grey



User

INFORMATION SHEET

Glove description

14T3500 Arco Red Cut Control System 1A Foam Nitrile-Coated Gloves

Approved to:

EN388:2016 Mechanical Risk 4.X.2.1.A
 ISO 13997
 BS EN420:2003 Size: 7-10

Table 1 – Levels of performance

Test	Level	Level	Level	Level	Level
	1	2	3	4	5
6.1 Abrasion resistance (number of cycles)	100	500	2000	8000	-
6.2 Blade cut resistance (index)	1,2	2,5	5,0	10,0	20,0
6.3 Tear resistance (N)	10	25	50	75	-
6.4 Puncture resistance (N)	20	80	100	150	-

Product Markings / Performance



Obsolescence

When stored properly the product will not suffer changes in the mechanical properties from the date of manufacture. Service life cannot be specified as it depends on the application and its the responsibility of user to ascertain the suitability of the glove for its intended use.

Maintenance

Both new and old gloves should be inspected before wearing to ensure that no damage is present before use. Laundering these gloves is not recommended. If wet allow to dry naturally

Warning

Performance levels relate to the palm area of the glove only. While wearing these gloves please ensure you keep a safe distance away from moving parts of machinery to minimize the risk of entanglement

Innocuousness

Whilst every effort is made to ensure the innocuousness of these products, there are certain chemicals used in the manufacturing process which may cause skin irritation to a small percentage of users. In the unlikely event of this happening, the product should not be used and Arco contacted for alternative products.

Storage and transport

When not in use, store in a well ventilated area away from extremes of temperature Never place heavy items on top of it. If possible, avoid excessive folding and preferably store it hanging vertically

Declaration of Conformity

Declaration of Conformity can be viewed and downloaded from <http://conformity.arco.co.uk>