

# CHEMSOL HG LITE



## LIGHTWEIGHT PROTECTIVE CLOTHING FOR THE FOOD INDUSTRY

Chemsol HG Lite is a range of lightweight, flexible garments developed for washdown applications in the food industry. This range is made from a material blend of PVC/PU offering long-lasting chemical protection and resistance to animal fat and food oils.

### FEATURES

- Anti-bacterial coating which prevents mould build-up
- Enhanced protection against animal fats and food oils
- Fully liquid proof
- Lightweight 305gm<sup>2</sup> PVC/PU
- Greater flexibility due to the PVC/PU blend
- Soft and durable fabric
- Stronger stitched and high frequency welded seams
- Bespoke options available to order on request



### ORDERING INFORMATION

#### Part Number:

- HLJC-EW** - Chemsol HG Lite Jacket with Collar
- HLJH-EW** - Chemsol HG Lite Jacket with Hood
- HLTE** - Chemsol HG Lite Trousers with Elasticated Waist
- HLBB-EA** - Chemsol HG Lite Bib 'n' Brace
- HLS15** - Chemsol HG Lite Sleeve
- HLA48/36** - Chemsol HG Lite Apron

### SUITABLE APPLICATIONS

#### Recommended applications include:

- Agriculture
- Dairy Industry
- Food Manufacturing
- Jet Washing
- Shipping
- Tank Cleaning



### TECHNICAL SPECIFICATIONS

#### OPTIONS

PRODUCT	PRODUCT OPTIONS				CODE
	Collar	Hood	Elasticated Wrists	Elasticated Ankles	
Jacket	✓	-	✓	-	HLJC-EW
	-	✓	✓	-	HLJH-EW
Trouser with Elasticated Waist	-	-	-	-	HLTE
Bib 'n' Brace	-	-	-	✓	HLBB-EA
Sleeve	-	-	-	-	HLS15
Apron	-	-	-	-	HLA48/36

#### SIZING

The following table reflects the dimensions of the four standard sizes. We also manufacture sizes outside the standard sizes, eg XS, XXL, XXXL etc. We also provide customers with the facility to order garments with dimensions to their own bespoke size.

SIZE	CHEST (cm)	BODY HEIGHT (cm)
S	90 - 98	162 - 168
M	98 - 106	168 - 174
L	106 - 114	174 - 180
XL	114 - 122	180 - 186

#### CERTIFICATION

EN 14605:2005  
+A1:2009



Type  
PB [4]

#### STORAGE AND MAINTENANCE

It is recommended that new Chemsol HG Lite garments are stored in their original packaging and clear of UV sources.

Once used it is recommended that the care instructions, as detailed on the label, are followed. To remove contamination, Chemsol HG Lite clothing should be rinsed down with cold water, and subsequently allowed to drip dry in the shade, clear of UV sources. Chemsol HG Lite clothing should be stored in a cool, dry and clean environment.

Advice: For reasons of hygiene the garments should preferably be worn by the same person.