

TECHNICAL

DATA SHEET Cut Control 3C Foam Nitrile Glove

Arco 10 Gauge seamless liner

Product Code: 14T3600

Sizes S. M. L. XL.

Approved to:

EN388:2016 4.X.4.2.C EN420:2003+ A1:2009 CAT II

Suitable For:

- Assemble Work
- · Light to Medium manufacturing

Glove Properties:

Foam Nitrile coated palms to provide great grip in wet, dry and oily conditions.

Seamless 10 gauge liner

HPPE-based liner is cool and comfortable

Black liner masks dirt for a longer life.

Amber colour to help easily identify cut protection at a glance.

Cuff Colour Sizing:

- 7 Blue
- 8 Green
- 9 Red
- 10 Black





User

INFORMATION SHEET

Glove description

Arco 10 Gauge seamless liner with Foam Nitrile coating

Approved to:

EEN388:2016 4.X.4.2.C EN420:2003+ A1:2009 CAT II

Product Markings / Performance

EN388: 2016





EN420

4.X.4.2.C

Table 1 — Levels of performance

Test	Level	Level	Level	Level	Level
	1	2	3	4	5
6.1 Abrasion resistance	100	500	2000	8000	-
(number of cycles)					
6.2 Blade cut resistance (index)	1,2	2,5	5,0	10,0	20,0
6.3 Tear resistance (N)	10	25	50	75	-
6.4 Puncture resistance (N)	20	60	100	150	-

Obsolescence

When stored properly the product will not suffer changes in the mechanical properties from the date of manufacture.

Service life cannot be specified as it depends on the application and its the responsibility of user to ascertain the suitability of the glove for its intended use.

Maintenance

Both new and old gloves should be inspected before wearing to ensure that no damage is present before use. Laundering these gloves is not recommended. If wet allow to dry naturally

Warning

Performance levels relate to the palm area of the glove only.

While wearing these gloves please ensure you keep a safe distance away from moving parts of machinery to minimize the risk of entanglement

Innocuousness

Whilst every effort is made to ensure the innocuousness of these products, there are certain chemicals used in the manufacturing process which may cause skin irritation to a small percentage of users. In the unlikely event of this happening, the product should not be used and Arco contacted for alternative products.

Storage and transport

When not in use, store in a well ventilated area away from extremes of temperature Never place heavy items on top of it. If possible, avoid excessive folding and preferably store it hanging vertically

Declaration of Conformity

Declaration of Conformity can be viewed and downloaded from http://conformity.arco.co.uk